

## Service Bulletin 01663

(Revision -, 08/2019)

# EasyGen 3000 Series / Remote Panel 3000 Series Display Contrast Value Unstable

#### Issue

EasyGen 3000 Series / Remote Panel 3000 Series devices may experience an increase in display contrast brightness

## **Description**

Contrast brightness may be affected when power-cycling the affected device. After multiple power cycles contrast may visibly deteriorate.

This does not affect other functionality of those units.

## **Affected Units**

The following top level part numbers are affected:

**EasyGen-3000 Series:** 8440-1936, 8440-1937, 8440-1935, 8440-1934, 8440-2030, 8440-2049, 8440-2046, 8440-2047, 8440-2043, 8440-2050, 8440-2051, 8440-2052, 8440-2053, 8440-2062, 8440-2063, 8440-2065, 8440-2066, 8440-2067, 8440-2064, 8440-2070, 8440-2071, 8440-2093, 8440-2095, 8440-2105, 8440-2109, 8440-2108, 8440-2106, 8440-2111, 8440-2112, 8440-2115, 8440-2119, 8440-2145, 8440-2146, 8440-2156, 8440-2185, 8440-2186, 8440-2191, 8440-2192, 8440-2195, 8440-2193, 8440-2206, 8440-2207, 8440-2216

**Remote Panel-3000 Series:** 8446-1051, 8446-1055, 8446-1056, 8446-1057, 8446-1058, 8446-1059, 8446-1062, 8446-1046, 8446-1048, 8446-1050

### **Corrective Action**

Use the two methods below to adjust the contrast/brightness in the field.

- 1. Navigate to Parameter > Configure display. At this screen, with the help of + and buttons, the contrast and brightness can be adjusted to the desired level.
- 2. Press and depress the STOP button for approximately 10 seconds. This action restores the default display settings for brightness and contrast.

**Note:** use this method only when your genset is already stopped.

More details to adjust contrast/brightness are available in the product manuals (37528, 37531, 37532, 37534) available at Woodward.com

#### **Customer Action**

Should you experience this issue and neither of the two corrective action methods above fit your application, contact your Woodward technical support or customer service representative for a firmware upgrade. You may need to return your affected unit(s) to Woodward. A Woodward representative will help generate a Return Authorization Number (RAN). Any cost incurred are evaluated per warranty terms and status of the affected unit(s).

Technical Bulletin 01663 p.2



PO Box 1519, Fort Collins CO 80522-1519, USA 1041 Woodward Way, Fort Collins CO 80524, USA Phone +1 (970) 482-5811 • Fax +1 (970) 498-3058

Email and Website—www.woodward.com

Woodward has company-owned plants, subsidiaries, and branches, as well as authorized distributors and other authorized service and sales facilities throughout the world.

Complete address / phone / fax / email information for all locations is available on our website.