

Coder 5.01-0 Release Notes

DATE:

October 21, 2009

BACKGROUND:

Version 5.01-0 is a new release of the Coder/Opsys

WARNING: To use this version GAP/Coder you must use GAP 2.18C or higher.

WARNING: To use this version GAP/Coder you must use SOS 3.4 or higher.

NEW FEATURES:

The major changes from 5.00 to 5.01 were:

- The **PCM_KNOCK** logic was overhauled to use a specification file
- The J1939 CAN logic was overhauled and replaced with a more complete set of library functions. This enables a full set of diagnostic message blocks ("DMx_MSG") which can be used for on-board diagnostics ("E-OBD") and supports sending long messages using CTS/RTS.
- The **EVENT_MGR** logic was overhauled to support OBD standards and to be more RAM and EE efficient
- Enhanced security in accordance with OBD standards
 - Flash memory is verified in the background continuously
 - The **SECURE** block was added to provide user-configurable Seed-Key download protection
 - Updated SID generator so that it produces a SID file which is not human-readable
- Updated SID schema in Coder, SOS and Toolkit to match new constructs
- Updated Pattern 15 logic in PCMHD and supported misfire detection
- Moved pre-injection and post-injection out to maximum 360 degrees
- Added **AI_UEGO** support for LSU 4.9 (requires MY10 PCMHD hardware version)
- Corrected merge file issues and enhanced the EEPROM save algorithm for #CAL parameters on low volume PCMHD controls

ISSUES:

The following knowledge base ("PID") issues were addressed in 5.01-0:

Issue #	Description	Solution
2179	Please add support for the Bosch Uego LSU 4.9 to AI_UEGO	LSU 4.9 Implemented
2477	Redundant CAN_WRITE - cyclic write in CANOPEN with redundant can	Fixed by improving code robustness
5191	MicroNet Backup error in CAN_P_STAT expansion chassis	Note added to Block Help for CAN_P_STAT advising setting the rate group fast enough to keep E_TIMEOUT up to date
7051	Utilize the size indicator in the CO_SDO download message. Set it automatically according to the size of the data in the WRITE_x blocks of the repeat group	Implemented
7491, 8593,	AppManager sometimes reports "Running" when the application is in fact unable to run	An additional state was added to AMService and AppManager 2.10 which reports "Inactive"

9271, 14402	because of a configuration error	for this circumstance
7951	EVENT_MGR.OVER_n does not override the message from being packed in the DM1 message	This was corrected with the complete EVENT_MGR rewrite
8593	see #7491 above	
8631, 10211	Error in Block C_FUNCTION when there is only one constant input of a given type with a zero value	This is as designed and has been explained in the Block Help for the C_FUNCTION block: Setting the only input to a constant zero value is a way to signal the compiler not to create code for this input
9271	see #7491 above	
10211	see #8631 above	
11491	PCMHD MIL block: When START_FL is true and then you change to another mode (BLINK_1 or BLINK_2) the block locks the CUR_FLT and TOTAL_FLT outputs where they were	The MIL block behavior has been more clearly explained in the Block Help
11513	PCMHD MIL block: When the START_FL is tuned false the block does not finish flashing the value currently being displayed before stopping.	Code corrected as part of the EVENT_MGR code rewrite
11671	Ladder Logic 2.10 does not work with NetSim	Modified simop.lib to make LL_VALUES update across rate groups
12632	Values from ZMINUS_ blocks with DATA_LOG_M are not synchronized with other rate group values	This situation arises because of when the DATA_LOG_M samples the data. It is set up to sample the data at the start of the rate group and before the ZMINUS_ blocks run. We tried sampling after the ZMINUS_ blocks run, but that introduced jitter depending on when the ZMINUS_ blocks executed in the longer rate groups. It was decided that the way it is, is less of an issue. The help for the ZMINUS_ blocks and the DATA_LOG_M blocks has been updated to describe this policy
12651, 14211	Backup data sometimes inconsistent with primary in MicroNet	The missing values were self-looping blocks (which creates a "state"). The Coder has been changed to detect blocks that are looped to themselves and create a "State" value that is passed to the backup CPU
13197	DATA_LOG_M Tunable Strings in Repeat Groups cause a general protection fault in the coder	This bug has been fixed in the Coder
13262	Pattern 18/19 Sync variability	Added description and explanation of behavior to EFI_P_CORE block in Block Help
13263	LATCH_AE block: Events.log.csv re-created after power cycle	The name of this file was changed to "ae_eventlog.csv" to overcome a one-period per file name limitation in the control's FTP

		implementation
13447	An application with no Servlink port does not allow a re-download --add suitable warning	Suitable warning added
13982	Entering a string value of "*" or "#" on a string input such as on the I_TO_STR block will cause a general protection fault in the coder	String parsing code in coder has been revamped and this bug has been corrected
13990	NV_LOG block on MicroNet and Atlas platforms: Count is wrong after a restart	Added missing read of the previous value to the start-up code
14015	LATCH_AE block: Events sometimes not written to the log file	This was because of a buffer overrun in the particular (stress test) application. The buffer has been adjusted appropriately to prevent this error
14039, 14169	After a reset of the CPU, the SIO Port does not function	This only occurred when the BAUD rate was being passed from another block. A problem with initializing the BAUD rate in this situation has been corrected
14075	When the control has a rate group slip, the SOS server loses its connection and it doesn't come back until you reset the control	This is by design for TCP SOS connections. If SOS were to continue running and reporting values, it might appear that the control was healthy. The Block Help has been updated to explain this behavior as well as how a rate group slip can be detected on a control with only serial communications
14087	The count output on the NV_LOG block in TMR does not update consistently. Sometimes it updates by multiple counts with each trigger, sometimes not.	The code was protected with a one-shot to prevent multiple increments
14088, 14222, 14365	I have seen this several times where resetting a control by entering and exiting IO Lock will cause a CPU to get stuck in the "stopping" state and not come back without a hard reset of the CPU.	This was caused by sending debug messages to the Debug COM port during the stop process. These messages have been removed
14091	Remove AI_KNOCK from template	Removed. The functionality of the block has been replaced with PCM_KNOCK
14107	MODBUS_S holding register during LNK_ERR	Modified the scaling to divide the default by the scaling in link error
14116	If I set a TMR CPU to use SNTP but give it an address that is not a valid SNTP server it will hang on boot-up for about 50 minutes	The SNTP code has an extremely long time-out. This has been addressed in the 5418-2918A and 5418-2566F footprints
14140	Misfire block high speed after boot (divide by 0 in MATLAB)	Corrected in code
14154	DM2 should be logged and not active. I think they are logged regardless of active	Fixed with EVENT_MGR changes
14164	DIVIDE block: Please add a description to Block Help to describe what happens when the divisor input is 0	Block Help updated: if IN_2 is zero the output is set to either +1E34 (if IN_1 is positive) or -1E34 (if IN_1 is negative)
	The output of the LAG block can become	

14165	"Not a number!" when the input is a large negative number like -1e38	Fixed in coder by not storing NAN values
14169	See #14039 above	
14171	MicroNet TMR - cal_all_ft_act process not getting serviced consistently	The priority of the cal_all_ft_act task was increased above the priority of the tNetTask to ensure regular servicing
14175	Will GAP 2.x or 3.x be supported by V&V?	Most of the testing was performed using GAP 3.0, but representative applications were tested in GAP 2.18C as well. Furthermore, many tests were performed in GAP3 to confirm that it produces equivalent ".cdr" files to GAP 2.18
14179	Cannot compile Redundant CAN Application	This was because of using a group of temporary files interleaved by the rate groups - causing unintentional variable sharing in this application. It has been corrected by creating a static array of files (one for each)
14184	The AI_SYNC block (ECM3) will not schedule on a tooth that has already been scheduled by EFI. Also if AI_SYNC manages to schedule on a tooth, EFI will be prevented from scheduling on that tooth.	Fixed scheduling of AI_SYNC
14195	Coder 5.00 fails with old Servlink servers. This was particularly observed with Watch Window Professional.	This was a bug introduced in version 5.00 which has been corrected in 5.01. The old "debug-table" interface has been removed from Servlink in 5.01
14197	It is possible to code using the VxWorks compiler with the debug option set. I don't think that compiling with that set is tested by V&V so it shouldn't be an option for the customers	The option has been removed in Coder 5.01
14198	Occasional MicroNet Plus rate group slips on start-up	System changes were implemented to prevent these rate group slips
14199	If there are two AI_MPU_ENG blocks in the application but only one defined in the EFI_CORE , a general protection fault in the Coder will result	There was a string compare to null (the undefined one) which has been corrected
14207	Increase tmp_blk count to 20 files for easYgen	Added capabilities to handle additional files in the Coder
14211	See #12651 above	
14216	We need to increase the number of states allowed per rate group in the MicroNet Plus	The Coder has been changed to allow 24192 states per rate group
14222	See #14088 above	
14225	AO_RM_DRV current split incorrect at zero demand	Corrected by only using the ACT_COMBO limiter if the NUM_GOOD input field is a constant
14232	The Atlas II Actuator output can go to Max value if the current demand gets very close to zero and the calibration offset is negative.	Corrected the library to clamp with ActWithDitherCal>0 instead of ActWithDither>0

14233	On the DATA_LOG_M block the start time is recorded as the stop time	In non-continuous mode (only), the DATA_LOG_M block was incrementing the start time with each collection cycle. This has been corrected
14234	The DATA_LOG_M block saves its files to different directories depending on CONTINUOUS mode	This is by design. Continuous files need to be saved in a RAM directory to prevent overusing flash memory when files are constantly being written. This has been explained in the Block Help
14245	PCMHD download failed when use PCMHD_LARGE_SCP	Corrected anticipated buffer size
14274	GAP application is sending some messages to DVP with incorrect length (CanOpen)	The DVP was expecting all messages to be truncated to minimum length. The control code has been adjusted to match this expectation
14283	MODBUS_M link errors on redundant MicroNet Plus	Changed the table so the message contains enough info for the other CPU to set the correct errors
14284	MODBUS_M exception errors on redundant MicroNet Plus	This was caused by confusion in RTU timing. Corrected by adding a floor of 10ms for RTU timing for each baud rate
14300	EGD_CON EGD_C_ field should be mandatory	Made mandatory in the template
14305	VxWorks 5.5.1 TFFS Corruption	VxWorks True Flash File System patch implemented
14306	AO_RM_DVR does not work as stated in the Block Help	Updated Block Help to accurately describe the behavior of this block
14308	Add string security for HMI SID Builder	Added missing write security calls to sidbuild.cpp for sidaddstring function in 5.01
14325	LATCH_AE can cause a general protection fault in the NetSim coder builder	Corrected an indexing bug in coder
14326	Tunable strings in GAP3 are represented with a tunable symbol followed by a quoted string in the coder file. The coder includes those quotes in the value	Updated coder string reading routine
14329	EGD Broadcast and Multicast functions for producers and consumers are not in NetSim	The EGD block had never been implemented for simulation. The necessary code has been added to 5.01
14331	PCMHD Flash Checksum Fault	Fixed in 5.01 by changing the flash checksum to use CRC instead of 2's complement
14342	EGD block: The Exchange ID is limited to a value of 0-255. It should allow a full short value	Changed range in template to 0-16383
14350	Change 200 Curve limitation (CAL_CURVE2 , CAL_CURVE3 , A_CURVE2 , A_CURVE3)	The limit was changed to 2000
14359	Please add a "remove application from autostart" feature to AppManager	Command added to AppManager and AMService on control

14365	See #14088 above	
14371	Multiple EVENT_MGR block and HMI_PT interaction issue	System was changed to handle case correctly
14376	2nd LON_MOD (LinkNet Module) in Expansion Chassis doesn't communicate	Addressing problem corrected in Coder
14382	Using pattern 14 with EDMHD_SPRK , IC100_SPRK or an IC1100SPRK block will cause the PCMHD to not start when power is applied	System was changed to handle case correctly
14402	See #7491 above	
14411	GAP3 Field help missing for Repeat Groups	Added missing logic to template building code
14419	Need more than 20 module files	Increased allowed number to 100
14441	IACT_EM and IACT_PCM don't work in the MicroNet Plus Expansion chassis	Addressing problem corrected in Coder
14452	Block Help describes the motor resolver sine fault incorrectly	Corrected Block Help
14453	The DITHER block help says D_RATE defines the frequency of the DITHER and should be $1 / 2 * D_RATE$. The actual frequency is $1 / D_RATE$	Corrected Block Help
14466, 14471	Tunable save can cause FBUS_M LINK_ERR and/or Servlink communication pauses	Changed the function "update_ee()" to time-slice during the EE save process. This allows lower priority tasks to have some time to run and eliminates communication time-out problems
14468	SYNCHRO.GEN-PHASE and BUS_PHASE help is incorrect	Corrected Block Help
14471	See #14466 above	
14514	Please update the block help and the MicroNet Hardware manual to explain that SIO will set the channel faults for a short time during a CPU change-over. Please elaborate and/or modify the exact wording as appropriate	Updated Block Help
14599	ACT_CTRL blocks in RTN chassis can lose the calibration on channel #1	Changed system to save the correct TEMP values for channel #1 in the RTN chassis

JNSUPPORTED BLOCKS:

The following is a list of blocks which are available in the Template and GAP Editor, but are not supported in the 5.01-0 release version of the coder (compiler):

- [CAL_ID](#)
- [CO_IC1100](#)
- [COIL_CNFG](#)
- [I_TO_NAN](#)
- [J1939_TJET](#)
- [PC104_ATL](#)

- **RATIO_LIM2**
- **TEMP_HIST**

NEWLY SUPPORTED BLOCKS:

The following is a list of blocks not supported in the previous coder (5.00-2) which are supported in 5.01-0:

- **PCM_KNOCK**

PART NUMBERS:

Version 5.01-0

Gap/Coder Part Number: 9927-1748

Master Kit: 9927-1333, 8928-1088, 1796-1068